

FIELD INSPECTION REPORT

Date of Inspection :	11/12/2020	District:	SIKHAN
Division :	RWD SIWAN-01	Length (km):	4.60 KM
Name of the Road:	SAHLAUR TO CHAUMUKHA (MIR)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U S	
b)	Condition of Surfacing	✓ S/U S	
c)	Riding Quality	✓ S/U S	
d)	Road Camber	✓ S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No provisions	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No Is being done	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Yet To be done	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U Yet To be done	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U Yet To be done	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No Roadwork up Yet To be done	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

MANOJ KUMAR.

NAME:

For Manoj Kumar
21/12/2020
(Signature)