

FIELD INSPECTION REPORT

Date Of Inspection 3/12/2020		District Bhujpur
Division PIR		Length (km): 2.370
Name of the Road:	Bichhiro TO Dharampur	
Scheme/Programme	MAINTENANCE	
Package No.: RM/BH/PIR/19/0009	Road Id No.: NEA220001654	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
SI No.	Parameters to be checked	Remarks
1	Pavment	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N A Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N A S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name:

Kamlesh Kumar

Designation

J-E

K. Kumar
3/12/2020
(Signature)