

FIELD INSPECTION REPORT

Date of Inspection : 7/12/20 District: Madhepura
 Division : Madhepura Length (km): 3.16 K.m
 Name of the Road: Budhna to Lakhsaj
 Scheme/Programme: MAINTENANCE MR-3054 (New)
 Package No.: Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/L
b)	Condition of Surfacing	✓ S/L
c)	Riding Quality	✓ S/L
d)	Road Camber	✓ S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Birendra Kumar
 J.E
 Madhepura
 NAME:

Birend
 7/12/20
 J.E
 (Signature)