

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Mandya
Division : Udupi District	Length (km): 7.986 km
Name of the Road: L 977 B 40 - 14979429	

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.: HEA 220001594

Status of the Project:

Ongoing/Completed/Under Maintenance

NOT APPROVED

Work is a case of:

New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	NA
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	Yes/No	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	Cross Drainage	S/SRI/U	NA
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture	Yes/No	NA
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NA
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NOT APPROVED

Ranjan
(Signature)
JE Udupi District

NAME: M. KUMAR