

FIELD EXPERIMENTAL RESULTS

Date of Inspection:	17.10.20	Inspector:	Subodh
Location:	Dist. Chhatisgarh	Length (km):	3.410
Name of the Road:	National Highway - 100		
Scheme/Programme:	MADRIDARCI		
Project No.:	17.10.20	Serial No.:	
Location of the Project:	Chhatisgarh		
Work is a carry-over	New Construction/Improvement/Maintenance		
1. General 2. Roadway			
a)	Overall condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Drainage Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of RCC Pavement.	Yes/No	
f)	Construction Joints provided or not (RCC Pavement)	Yes/No	
g)	Composition of Bank Slope & relevant if any	Yes/No	
3. Structures			
a)	Condition of road walls in frame pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
4. Safety			
a)	Whether sign boards/informatory/cautionary Board/Icon & 200m advance pavement road markings are provided and maintained	Yes/No	
5. Others			
a)	Status of ATR's & any others		

Overall Rating: 4

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

WORK HAS NOT STARTED.

NAME: _____

DESIGNATION:

7/12/20
+ E
Bavapne