

## FIELD INSPECTION REPORT

<b>Date of Inspection:05.12.2020</b>		<b>District:- Sitamarhi.</b>
<b>Division:-RWD, Works Div. Pupri.</b>		<b>Length (km):-5.03</b>
<b>Name of the Road:- Muroul to Ratwara Gate Path</b>		
<b>Scheme/Programme:-</b>	<b>MAINTENANCE</b>	
<b>Package No.:- MR-N/19-20 Pupri/04</b>	<b>Road Id No.: NEA220001707</b>	
<b>Status of the Project:</b>		<b>Ongoing/Completed/Under Maintenance</b>
<b>Work is a case of:</b>		<b>New Connectivity/Up gradation/ Maintenance</b>
<b>Sl. No.</b>	<b>Parameters to be checked</b>	<b>Remarks</b>
1.	<b>Pavement</b>	
a)	<b>Road Junction condition</b>	S/U
b)	<b>Condition of Surfacing</b>	S/U
c)	<b>Riding Quality</b>	S/U
d)	<b>Road Camber</b>	S/U
e)	<b>Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement</b>	Yes/No
f)	<b>Contraction Joints provided or not (CC Pavement)</b>	Yes/No
g)	<b>Compaction of flank/slope &amp; raincuts if any</b>	Yes/No
2.	<b>Cross Drainage</b>	
a)	<b>Condition of head walls in Hume pipe culverts including its painting</b>	S/SRI/U
b)	<b>Condition of Abutments &amp; Wing walls, Slab in RCC culverts</b>	S/SRI/U
c)	<b>Condition of railing/slab/approach for bridges</b>	S/SRI/U
3.	<b>Road Furniture</b>	
a)	<b>Whether sing board/informatory/cautionary Board/ Km &amp; 200m stones/Pavement road marking are provided and maintained</b>	Yes/No
4.	<b>Compliance History</b>	
a)	<b>Status of ATR's &amp; any others</b>	

Overall Rating : *Technical bid submitted for new MR to H&D.*  
*N/A.*

<b>Satisfactory (S)</b>	
<b>Satisfactory but requires Improvement (SRI)</b>	
<b>Unsatisfactory (U)</b>	

Name:- *Bijay Kumar Pandey*

*Bijay Kumar Pandey*  
*05/12/2020*  
*(Signature)*

DESIGNATION:- *JE*