

FIELD INSPECTION REPORT

Date of Inspection: 07-12-20	District: Sakon
Division: R.N.D. Chapra-2	Length (km): 4.150 km
Name of the Road: Dakhilabad to Mirzapur	
Scheme/Programme:	MAINTENANCE
Package No.: M.R.N/19-20 Chapra-2	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a cast-off:	New Connectivity/Up-gradation/ Maintenance

a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC-Pavement)	Yes/No
g)	Compaction of flank/slope & reincuts if any	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing-walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work has not started.

(Signature) J-1220
J.E
Ranapur

NAME:

DESIGNATION: