

FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Darbhanga.
Division:	RWD Wm (Div) Darbhanga-2	Length(Km):	2.05 KM.
Name of Road:	L045 to Bhajawahanikare.		
Scheme/Programme:	Maintenance MR-3054 (New-Maint. policy-2018).		
Package No.	_____	Road Id No.	_____
Status of the Project:	Ongoing/Completed/ Under Maintenance _____		
Work is a case of :	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No
3	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	0 S *
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: KUMAR CHANDRAT.
Designation: A.E.T.T. ENGINEER.

(Signature)
सहायक अभियन्ता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, सिंहबाड़ा

* Heavily submerged & flow of water during flood water period full constructed length was fully damaged & at about end point road was badly damaged.
AS per Guidelines given by SEC (R&S) Govt of Bihar, for easily movement of vehicle temporary respiration work has been done.
Work will be starting soon.