

2

FIELD INSPECTION REPORT


Date of Inspection:	05.12.2020	District:	Darbhanga
Division:	RWD works(Div) Darbhanga-2	Length(Km):	2.00 KM.
Name of Road:	T02 to Agyanpur		
Scheme/Programme:	Maintenance (MR-3054, New Maint. policy-2018)		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance		—
Work is a case of:	New Connectivity/Up gradation/ Maintenance		✓

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank /slope & raincuts if any	Yes/No NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whethersign boards/ informative/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No NA
3	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating:

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Not applicable ✓



05/12/2020

(Signature)
 सहायक अभियन्ता
 ग्रामीण कार्य विभाग
 कार्य अवर प्रमंडल, सिंहबाजार

Name:

Designation: