

## FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020.		District:- Sitamarhi.
Division:-RWD, Works Div. Pupri.		Length (km):- 3.130 km.
Name of the Road:-Sursand Pupri R/O Road To Chandpatti.		
Scheme/Programme:-		MAINTENANCE
Package No.:- MR-N/19-20 Pupri/02		Road Id No.: NEA220002149
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks -
1.	Pavement	work to be started
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railing/slab/approach for bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : SRI

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name:- Praveen K R Pandey

DESIGNATION:- JE

(Signature)

*Praveen*  
3-12-20