# FIELD INSPECTION REPORT

| | | | |
|---|---|---|---|
| **Date of Inspection :** 3/1/20 | | **District:** Araria | |
| **Division :** Araria | | **Length (km):** 6.970 | |
| **Name of the Road:** NH-57 Paiktola Via Kushiargaon Rd. Part-B | | | |
| **Scheme/Programme:** | MAINTENANCE | | |
| **Package No.:** | | **Road Id No.:** SH M — 839 | |
| **Status of the Project:** | Ongoing/Completed/Under Maintenance | | |
| **Work is a case of:** | New Connectivity/Up gradation/ Maintenance | | |

| Sl. No. | Parameters to be checked | Remarks |
|---|---|---|
| **1.** | **Pavement** | |
| a) | Road Junction condition | S/U |
| b) | Condition of Surfacing | S/U |
| c) | Riding Quality | S/U |
| d) | Road Camber | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No N.A. |
| **2.** | **Cross Drainage** | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| **3.** | **Road Furniture** | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No |
| **4.** | **Compliance History** | |
| a) | Status of ATR's & any others | |

Overall Rating :

| | |
|---|---|
| **Satisfactory (S)** | |
| **Satisfactory but requires Improvement (SRI)** | |
| **Unsatisfactory (U)** | |

Note :- Under Tender Process

3/1/20

**(Signature)**

**NAME:** Arvind Kumar Das

**DESIGNATION:**