

FIELD INSPECTION REPORT

MARWADI

Date of Inspection :	07.12.2020	District:	Muzaffarpur
Division :	Muzaffarpur West	Length (km):	2.8 km
Name of the Road:	NH 102 Pakri Chowk Se Kodariya road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S S/U	
b)	Condition of Surfacing	S S/U	
c)	Riding Quality	S S/U	
d)	Road Camber	S S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No	
g)	Compaction of flank/slope & raincuts if any	S Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	Not done - S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Not done - S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	Not done - S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Not A/Hed Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

(Signature)

NAME: Jitendra Kumar

DESIGNATION: JE