

FIELD INSPECTION REPORT

Date of Inspection : 04.12.20.	District: Muzaffarpur
Division : RWD Muzaffarpur	Length (km): 4.30 km
Name of the Road: Huzar - Pichpur - Path.	
Scheme/Programme: MAINTENANCE	
Package No.: 249 MBD/2021-21	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	H/A S/U
b)	Condition of Surfacing	H/A S/U
c)	Riding Quality	H/A S/U
d)	Road Camber	H/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	H/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H/A Yes/No
g)	Compaction of flank/slope & raincuts if any	H/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	H/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	H/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	H/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	H/A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	H/A

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

[Signature]
04.12.20.

(Signature)

NAME:

DESIGNATION:

[Signature]
4/12/2020
S.E.