

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District:	MUZAFFARPUR
Division :	MUZAFFARPUR WEST	Length (km):	2.7 km
Name of the Road:	NH-28 Cold Stone Chowk - Moxsandi Path		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	RD - 249 MBD/2020-21
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U
c)	Riding Quality	N/A S/U
d)	Road Camber	N/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature) 4/12/20

NAME: Shrinu Kumar

DESIGNATION: J.E

4/12/20
AS