

Latitude: 26.073972
 Longitude: 85.120083
 Elevation: 38.54m
 Accuracy: 14.0m
 Time: 07-12-2020 15:08

FIELD INSPECTION REPORT

Date of Inspection: 7-12-20

District: Murshidabad

FIELD INSPECTION REPORT

Date of Inspection: 7-12-20	District: Murshidabad
Division: PWD Murshidabad	Length (km):
Name of the Road: Kalyan Nigamat - Jagatithal Bazar	
Scheme/Programme: MAINTENANCE	
Package No.: PWD/Murshidabad/19	Road Id No.: NEA-32000265
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A S/U
b)	Condition of Surfacing	N.A S/U
c)	Riding Quality	N.A S/U
d)	Road Camber	N.A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	N.A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N.A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	N.A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

7-12-20
 JE
 (Signature)