

# FIELD INSPECTION REPORT

Date of Inspection :		District: <u>muzaffarpur</u>
Division : <u>muzaffarpur G-2</u>		Length (km): <u>6.8801 km</u>
Name of the Road: <u>Jaguar se lalehangpur</u>		
Scheme/Programme:		MAINTENANCE <u>MR 3054</u>
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>N/A</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>N/A</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>N/A</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>N/A</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>N/A</u>
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	<u>NO</u>

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	<u>U</u>

some portion of road crest damage due to flood in 2020

7.12.2020  
(Signature)

NAME: umesh patwary

DESIGNATION: DE