

FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020	District: Banka
Division : Banka - 1	Length (km): 4.65
Name of the Road: Mirzapur - Kirampur Road - Pahalampur via Parasia	
Scheme/Programme:	MAINTENANCE
Package No.: RM/BA/BAN/19/0005	Road Id No.: NEA 22000416
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U Ongoing
b)	Condition of Surfacing	S/U Ongoing
c)	Riding Quality	S/U Ongoing
d)	Road Camber	S/U Ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U Ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: PRITHAM KUMAR
DESIGNATION: A.E

Pritam
04.12.2020
(Signature)