In Tonder Process.

FIELD INSPECTION REPORT

Date of Inspection:			District:	Fanui	
Division: Januic			Length (km): 2.835 Km.		
Name of	the Road:	Jamui LKR Pu	of path.	-lakhompus	stain p
Scheme/I	Programme:	MAINTENANCE			
Package	No .: MR-N	119-20/7/mui-201	Road Id No.:	NEA220	211500
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is a case of: New Connectivity/Up gradation/ Maintenance			article and the second second		
Sl. No.		Parameters to be	checked		Remarks
1.	Pavement	a company			a seek
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber :			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
SHOWARD WENTER	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a) ू	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4.	Compliance H	Story .			
a)	Status of ATR'	& any others			

Overall Rating

Satisfactory (S)	1	1.45.
Satisfactory but requires Improvement (SRI)	1 -	
Unsatisfactory (U)		•

untz (12/2)

Executive Engineer RWD Worksightstop, Jamui

NAME: