

## FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020	District: Jamui	
Division : Jamui	Length (km): 3.30 Km	
Name of the Road: Kenuhar Rotarpur Marwiya PWD Road (kalk pathar) - Bhandra.		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N19-20 Jamui-18 Road Id No.: WIEA2200078870		
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/A
b)	Condition of Surfacing	S/A
c)	Riding Quality	S/A
d)	Road Camber	S/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
1.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
1.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
1.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started -

  
07/12/2020

(Signature)

NAME:

(Ashok Kumar Agre)  
AE, R&D, Laxmanpur

DESIGNATION: