

on going Rec

FIELD INSPECTION REPORT

Date of Inspection : 03.10.21	District: Chhappur
Division : ATR	Length (km): 2.2 km
Name of the Road: Babura to Subapur Road	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sr. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - NA work
b)	Condition of Surfacing	S/U - N.A. Shutter
c)	Riding Quality	S/U - N.A. S. B. M
d)	Road Camber	S/U - N.A. W. B. M
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	N.A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
3.10.21
(Signature)

SCALE