

FIELD INSPECTION REPORT

Date of Inspection :	03.12.20	District:	Shimoga
Division :	Aza	Length (km):	1.50 km
Name of the Road:	Kulhampur Bus Stand to Markandapur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S/U	N.A
b)	Condition of Surfacing	S/U	N.A
c)	Riding Quality	S/U	N.A
d)	Road Camber	S/U	N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N.A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No	N.A
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	N.A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Leg S. B and W. D. H. Gouda started

Signature
3.10.20

NAME: