FIELD INSPECTION REPORT

Date of I	inspection :	3-12-2020	District: Renters	
Division: Stafam-1			Length (km): 0.000 km	
Name of	the Road:	CTT. Pos		-
Acceptable to the second	Programme:	MAINTENA	Road Id No.:	
Package		10 1/10-11	pleted/Under Maintenance	
mention that belief in the best	f the Project:	New Connect	ivity/Up gradation/ Maintenance	-
Work is a case of:		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
1	Gross Deute	ige.		artini and
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
13/	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Collegiates	History	为一位产品,或"ACAL"	
a)	Status of AT	R's & any other	rs	1

Overall Rating

Satisfactory (S)	_ S
Satisfactory but requires Improvement (SRI)	V
Unsatisfactory (U)	

MOTE - WON on Primes

(Signature)

NAME:

UMESH

DESIGNATION:

15