

FIELD INSPECTION REPORT

Date of Inspection : 5/11/20
 Division : *Mechanigay*
 Name of the Road : *jalapine main road to Muthaya lake*
 Scheme/Programme : MAINTENANCE
 Package No.: MR-N/20-21, *Mechanigay*
 Status of the Project : ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance

District: *Solan*
 Length (km): *1.5 km*

Sl. No.	Parameters to be checked	Remarks
1.	Pavement <i>B.T. work not started</i>	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U
c)	Riding Quality	N/A S/U
d)	Road Camber	N/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	" Yes/No
g)	Compaction of flank slope & raincuts if any <i>partly done</i>	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	" S/SRI/U
c)	Condition of railings/slab approach for Bridges	" S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No agg

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME: *Ram Sagar Das*
J-E

RS
 5/11/20
 (Signature)