

FIELD INSPECTION REPORT

Date of Inspection :		District:	
Division :		Length (km): 0.81	
Name of the Road: Siriga Mahuama PMGSY to Salamusa Bazar			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	(S)
b)	Condition of Surfacing	✓S/U	(S)
c)	Riding Quality	✓S/U	(S)
d)	Road Camber	✓S/U	(S)
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No	NO
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	(Yes)
4.	Compliance History		
a)	Status of ATR's & any others	NO ATR	

Overall Rating :

Satisfactory (S)	15'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ajay Kumar Tiwari
6/12/2020
JE

Ajay Kumar Tiwari
(Signature)

NAME: AJAY KUMAR TIWARI
DESIGNATION: E.E.