

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Gobalgarh</u>
Division : <u>Gobalgarh-1</u>	Length (km): <u>3.80</u>
Name of the Road: <u>Sasamasa NH 28 to Bakhari via Kumbhrotund</u>	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	<u>work not started</u>
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U <u>N/A</u>
b)	Condition of Surfacing	S/U <u>N/A</u>
c)	Riding Quality	S/U <u>N/A</u>
d)	Road Camber	S/U <u>N/A</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>N/A</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>N/A</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No <u>N/A</u>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>N/A</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>N/A</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>N/A</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <u>N/A</u>
4.	Compliance History	
a)	Status of ATR's & any others	<u>N/A</u>

Overall Rating :

Satisfactory (S)	<u>N/A</u>
Satisfactory but requires Improvement (SRI)	<u>N/A</u>
Unsatisfactory (U)	<u>N/A</u>

Pranav
11/12/2020
JE

Pranav
(Signature)

NAME: AJAY KUMAR TIWARI
DESIGNATION: E.E.