FIELD INSPECTION REPORT

Date of Inspection: 3-12-2020			District: Rohdon	
Division: Sasgam-1			Length (km): 1.273 Km	
A STATE OF THE	Programme:	MAINTENANCE	1 to Basant per	
Package	THE RESERVE AND ADDRESS OF THE PARTY OF THE	MAINTENANCE	Road Id No.:	
-	f the Project:	Ongoing/Comple	ted/Under Maintenance	
and the second second	a case of:		y/Up gradation/ Maintenance	
SI. No.	Parameters to be checked			Remarks
1,	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ð	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
4	Cross Production			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Purniture			24
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
不	Condition Harby T.			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	1 2
Unsatisfactory (U)	

NOTE- ONLONG WORL

3/12/2020 (Signature)

NAME:

Umoth

DESIGNATION:

JE.