

# FIELD INSPECTION REPORT

|                                                               |                   |
|---------------------------------------------------------------|-------------------|
| Date of Inspection : 3.12.2020                                | District: Buxar   |
| Division : R.W.D. Buxar                                       | Length (km): 5.95 |
| Name of the Road: Kachhi Indaur                               |                   |
| Scheme/Programme: MAINTENANCE                                 |                   |
| Package No.: MR-N/19-20, Buxar/04                             | Road Id No.: -    |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                   |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                   |

| Sl. No. | Parameters to be checked                                                                                        | Remarks      |
|---------|-----------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | <b>Pavement</b>                                                                                                 |              |
| a)      | Road Junction condition                                                                                         | ✓S/U         |
| b)      | Condition of Surfacing                                                                                          | ✓S/U         |
| c)      | Riding Quality                                                                                                  | ✓S/U         |
| d)      | Road Camber                                                                                                     | ✓S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No NA    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No NA    |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | ✓Yes/No NA   |
| 2.      | <b>Cross Drainage</b>                                                                                           |              |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | ✓S/SRI/U     |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | ✓S/SRI/U     |
| 3.      | <b>Road Furniture</b>                                                                                           |              |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓Yes/No |
| 4.      | <b>Compliance History</b>                                                                                       |              |
| a)      | Status of ATR's & any others                                                                                    | No           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | ✓ |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

3.12.2020  
JB

NAME:

Signature  
03/12/20  
OK