

FIELD INSPECTION REPORT

Date of Inspection: 07.12.2020		District: N. Champaran
Division: Pethia		Length (km): 2.708.4
Name of the Road: Kation Inter of Doo and Baital chand via Dhangacholi		
Scheme/Programme: MAINTENANCE		- Police Line.
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance 01/9/2019	
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maint.	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
(Signature)

NAME: CONIL KUMAR

DESIGNATION: J.E