## FIELD INSPECTION REPORT

Date of I	nspection: 07/12/2020 D	District: Tanw'	,	
Division: Jaruw Length (km): 3.270km				
	the Road: Sikandra Nawado	PWD Road to Gablar	· · ·	
	rogramme: MAINTENANCE		E CELE	
Package	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Road Id No.: 28411 0319	305	
	the Project: Ongoing/Completed/U	nder Maintenance		
	- to the Commodity of	gradation/ Maintenance		
SI. No.	Parameters to be	checked	Remarks	
1.	Pavement			
a)	Road Junction condition		<b>~8</b> /U	
b)	Condition of Surfacing		<i>√8/</i> U	
c)	Riding Quality		<i>√8/</i> U	
d)	Road Camber		√S/U	
e)	Whether free from defects such aggregates in case of CC Pavement.	as visible cracks, exposed	Yes/No N/A	
f)	Contraction Joints provided or not (CC	C Pavement)	Yes/No N/A)	
g)	Compaction of flank/slope & raincuts	if any	Yes/No	
2.	Cross Drainage	Elizabeth a second a	The state of the s	
a)	Condition of head walls in Hume pipe	culverts including its painting	SISRIAU work has not bee	·?
b)	Condition of Abutment & Wing walls,	, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for	r Bridges	S/ <del>SRI/U</del>	
3.	Road Furniture			
a)	Whether sign boards/informatory/ca stones/Pavement road markings are pr	utionary Board/km & 200m ovided and maintained	Yes/No	
	Compliance History	A CONTRACTOR OF THE PARTY OF TH		
a)	Status of ATR's & any others		AM	

Overall Rating

Satisfactory (S)	ري ا
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

A EININO

Expensive Engineers (Signature) ision

NAME:

**DESIGNATION:**