FIELD INSPECTION REPORT

Date of Inspection: 08-12-2020			District: Awayaba	-	
Division: Dandragar			Length (km): 1.80 x -		
	the Road:	Kall To Gra	ini		
-	Programme:	MAINTENANCE		Late Value	
Packago		10 1 10 1	Road Id No.:		
	f the Project:		ted/Under Maintenance y/Up gradation/ Maintenance		
The state of the s		TOTAL CONTRACTOR OF THE PARTY O	to be checked Remarks		
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/N			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnit	ure			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others				
CONTRACTOR NO. 1881	A STREET, STRE				

Overall Rating

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Tenderof shis Road is not decided.

(Signature) E

NAME: Shubhan kumar

DESIGNATION: J.F.