FIELD INSPECTION REPORT

Date of Inspection : 2026 District:		int champara	
Division: Buthit		Length (km):	
R. Hith scho	alokot in	Ja Tola	
19-20 Beath -31	Road Id No.:	MI-MARE	
Ongoing/Completed/Under Maintenance			
New Connectivity/Up gradation/ Maintenance			
֡	R. High & Che MAINTENANCE 13-20 Beath 31 Ongoing Completed	Length (km): R. High Long to Jole MAINTENANCE 13-10 Beath 31 Road Id No.: Ongoing/Completed/Under Mainten	

SI. No.	Parameters to be checked	Remarks	
I.	Pavement		
a)	Road Junction condition	S/U }	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges , S/SF		
3.	Road Furniture		
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
	Compliance History		
) [Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	٤
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Bosnicha formal

DESIGNATION: J.E