## FIELD INSPECTION REPORT

Date of Inspection: 712 w		District: Mayava		
Division: Wojana		Length (Km):- 0.400		
Name of l	Road: prip magara B.	District:- Majara  Length (Km):- 0.400  Whom' Road to Ramumia Line Colony per Road.  Maintenance	Wis Khrods	
Scheme/Programme:-		Maintenance	Maintenance	
Package No.:- New MR.		Road ID No.:-		
Status of Project: Surface busses		- Ongoing/Complete/Under Maintenance		
Work is a case of :-		New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be cheeked		Remarks	
1.	Pavement			
a)	Road Junction Condition		S/U	
b)	Condition of Surface -		S/U	
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f)	Contruction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b) -	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained		Yes/No	
4.	Compliance History		TO WE LEAD TO	
a)	Status of ATR's & any others		140.	

Overall Rating:

Satisfactory (S)	\$
Satisfactory but requires Inprovement (SRI)	
Unsatisfactory (U)	

(Signature) 7.12.20
56/Work