


FIELD INSPECTION REPORT

Date of Inspection :- 7.12.20		District :- Khajawa	
Division :- Khajawa		Length (Km) :- 0.700	
Name of Road :- Bhodas to Dhan Phumant Bishunpur Road part - II			
Scheme/Programme :- New MR		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- Surber done		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Upgradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Constrution Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 7.12.20.
 J E/Khajawa