


## FIELD INSPECTION REPORT

Date of Inspection :- 7.12.20		District :- Khajuraho
Division :- Khajuraho		Length (Km) :- 0.700
Name of Road :- Bakhtiyarpur Gauri Me Phakurwar ke Samne Swatantrata Senani Gauri Me ke Ghar se Shadi Ghar		
Scheme/Programme :- New M.R.		Maintenance :- Yodav ke Ghar Tak Sadak. Khajuraho.
Package No. :-		Road ID No. :-
Status of Project :- Surface Dressing		Ongoing/Complete/Under Maintenance
Work is a case of :-		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction Condition	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

  
 7.12.20  
 J E. Hama