EIELD INSPECTION REPORT

	1 Inspection: 6/12/20 District: East cham 1 Length (km): 1.25 Kg	
	of the Road: To 1 Dankan Chorok to Sundar	
	e/Programme: MAINTENANCE New Maintenance	2018 ()
Packag	Road Id No.: 2178516	2018
-	Ongoing/Completed/Under Maintenance	2833
Work i	s a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	0.00
b)	Condition of Surfacing	\$/0
c)	Riding Quality P. A	S/()
d)	Road Camber	S/U
	Whather from Committee	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	1

This Road Under c/s procen

(Signature)

NAME: SAMIAY CUMAR

DESIGNATION: Assitant Engineer, Raxaul