

Inspection of Roads Under MR (3054) in Chausa Block

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Buxar	
Division : Buxar		Length (km): 2.000	
Name of the Road: Chausa - Moharia Road to Dihari via Rohanighat Under MR(3054) New Policy			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/ <input checked="" type="checkbox"/> Completed/ <input checked="" type="checkbox"/> Under Maintenance			
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input checked="" type="checkbox"/> Up gradation/ <input checked="" type="checkbox"/> Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No	N.A.
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N.A.
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

M. B. S. Ch
03.12.2020
(Signature)

NAME: Maya Nand Prasad

DESIGNATION: J. E.