FIELD INSPECTION REPORT

Date o	f Inspection: Dr	- 10	Later Land		
Date of Inspection: 05-12-2020 Division: (40/20/2019-2			District: Grobalgani		
Name of the Road: Vishunbura to Jalla			Length (km): 3.70 Km		
Schem	e/Programme:	MAINTENANCE	Jallalpur		
Packag	ge No .: MR-N 19-	JUNIO ENVINCE			
Package No.: MR-N 19-20 (nopology 02/12) Road Id No.: Status of the Project: Ongoing/Completed/Under Maintanance Work is a company of the Project of the P		Road Id No.:			
***		New Connectivity I In gradetic (1)			
Sl. No.	is a case of: New Connectivity/Up gradation/ Maintenance Maintenance				
1.	Payement Remark				
a)	Road Junction condition				
				S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			8/0	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			S/U	
f)				Yes/No	
g)	Contraction Joints provided or not (CC Pavement)			Yes/No	
-40	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture			S/SRI/U	
100	the same of the sa				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance Hi	story			
a)	Status of ATR's	& any others		NO	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	_

OS-N-20 (Signature)

NAME: Subhash chandra Verma

DESIGNATION: ンモ