FIELD INSPECTION REPORT

ate of Ir	ispection: 65	./2.2020 Dist	rict: Banka	
Division :	ion: Banka-1 Length (km): 0.660			
The state of the s	of the Road: Rampus Rampanisa to the attay			
Color and an included in the color and an entire		A CONTRACT OF THE PARTY OF THE	Control of the contro	
Package	The second secon	The same of the sa	d Id No.: 20703508	109
White the same of	the Project:	Ongoing/Completed/Unde		
Olek transmi	a case of:	New Connectivity/Up gra	dation/ Maintenance	
Sl. No.		Parameters to be ch	ccked	Remarks
1.	Pavement			
a)	Road Junction	oad Junction condition		√S/U
b)	Condition of Surfacing			S/U
c)	Riding Qualit	liding Quality		S/U
d)	Road Camber		√S/U	
c)	Whether free aggregates in	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ,
f)	Contraction J	ints provided or not (CC Pavement)		Yes/No
g)	Compaction of	of flank/slope & raincuts if any		X es/No
2,	Cross Drainage			
a)	Condition of	ion of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of	of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of	f railings/slab/approach for Bridges		S/SRI/U
3.	Road Furnit	lure		- 1
a)	Whether sig stones/Paven	n boards/informatory/cauti cent road markings are prov	onary Board/km & 200m ided and maintained	Yes/No
4	Compliance	History		
a)	Status of AT	R's & any others		CRATTE WARREND CONTROL

Overall Rating

	Satisfactory (S)
2.	Satisfactory but requires Improvement (SRI)
fis factory	Unsatisfactory (U)
	Unsatisfactory (U)

(Signature) 20 20

NAME:

DESIGNATION: