

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Mungel
Division: Khagaria Town		Length (km): 1-9.8
Name of the Road: Asarganj to Sajha		
Scheme/Programme: MAINTENANCE		
Package No.: 70		Road Id No.: S.N. 7
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Lip gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road function condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. No P.C.C.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement) No P.C.C.	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shailendra Kumar

(Signature)

NAME: