

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District :	Munger
Division :	Kharagpur-Togara	Length (Km) :	1.0
Name of the Road :	Jorari to Kharag		
Scheme/Programme :	MAINTENANCE		
Package No. :	N/A	Road Id No. :	208038083-6
Status of the Project :	Ongoing/Completed/Under Maintenance ✓		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	out of 5 year maintenance
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME :

DESIGNATION :

Shailendra K.

[Signature]

(Signature)