FIELD INSPECTION REPORT

Divisio		03/12/2020	District: Janu'		
	Janu		Length (km):		
	Programme:	Kandra Na wade MAINTENANCE	PWP road to Palsa L	Buzuze Road	
Packag		CONTROL AND	Road Id No.: 2080 410 4	001	
	of the Project:	Ongoing/Completed/	Under Maintenance	0.21	
	s a case of:	New Connectivity/Ur	gradation/ Mainterance		
Sl. No.		Parameters to b	e checked:	Remarks	
1.	Pavement				
a)	Road Junction	condition	4 - 10 and 10 an	√8/U	
b)	Condition of S	urfacing		_8/U	
c)	Riding Quality			√\$/U	5
d)	Road Camber			VS/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/NW/A	
f)	Contraction Joints provided or not (CC Pavement)			Yes/NoND	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	e distriction			
a)	Condition of he	ad walls in Hume pipe	culverts including its painting	S/SRI/U WOOK ha	pi
b)	Condition of A	outment & Wing walls,	Slab in RCC culverts	S/SRI/U NA	lo
c)	Condition of ra	lings/slab/approach for	Bridges	S/SRIAU NO	
3.	Road Fornitur	D	1. 283280		
a)	Whether sign stones/Pavemen	boards/informatory/cau t road markings are pro	ntionary Board/km & 200m	Yes/No/	
	compliante at	Story 4. ""	Company of the Compan		
a)	Status of ATR's	& any others		NIA	

Overall Rating

Satisfactory (S)	131
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

311-110

(Signature)

NAME:

DESIGNATION: