

Date of inspection : 03-12-2020  
 Division : Tiruvengudi  
 Name of the Road: Kanyara North to Bishnara via Mondal Tola (99bb, pur kar)  
 Scheme/Programme: MAINTENANCE  
 Package No.:  
 Road Id No.:  
 Status of the Project: ☒ New Connectivity/U/p gradation/ Maintenance  
☐ Ongoing/Completed/Under Maintenance  
 Work is a case of:

| Sl. No. | Parameters to be checked                                                                                             | Remarks          |
|---------|----------------------------------------------------------------------------------------------------------------------|------------------|
| 1.      | Pavement                                                                                                             |                  |
| a)      | Road Junction condition                                                                                              | Not applicable   |
| b)      | Condition of Surfacing                                                                                               | N.A. S/U         |
| c)      | Riding Quality                                                                                                       | N.A. S/U         |
| d)      | Road Camber                                                                                                          | N.A. S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | N.A. Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | N.A. Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | N.A. Yes/No      |
| 2.      | Cross Drainage                                                                                                       |                  |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | N.A. S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | N.A. S/SRI/U     |
| c)      | Condition of railings/slab approach for Bridges                                                                      | N.A. S/SRI/U     |
| 3.      | Road Furniture                                                                                                       | Not applicable   |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No           |
| 4.      | Compliance History                                                                                                   | Work not started |
| a)      | Status of ATR's & any others                                                                                         |                  |

|                                             |                |
|---------------------------------------------|----------------|
| Satisfactory (S)                            | Not applicable |
| Satisfactory but requires Improvement (SRI) | "              |
| Unsatisfactory (U)                          | "              |

Signature  
 03/12/20  
 S.D.O  
 Tiruvengudi

NAME: Jeyaraj Kumar  
 S.D.O. Tiruvengudi  
 RMD, Tiruvengudi