

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Supaul
Division : Trivenigangj	Length (km): 0.122 km
Name of the Road: Const. of Rcc Road around the additional primary Health Centre building at Rajeswari	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 21005108041
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/A
b)	Condition of Surfacing	S/A
c)	Riding Quality	S/A
d)	Road Camber	S/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

NAME: SURENDRA KUMAR
S.D.O. RWD
21/11/20

(Signature)

(सुरेंद्र कुमार)
अवर-प्रो. प्रमुख विभागीय
राजेश्वरी का प्रमाणित
03/12/20



REDMI NOTE 8
AI QUAD CAMERA