

FIELD INSPECTION REPORT

Date of Inspection :	6.12.2020	District:	
Division :	Balsi	Length (km):	3.0 KM
Name of the Road:	Asja-tola to Milk Tola shsi via khottapara chynamai road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of C/C Pavement.	Yes/No NA
f)	Contraction Joints provided or not (C/C Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI NA
b)	Condition of Abutment & Wing walls, Slab in R/C/C culverts	S/SRI NA
c)	Condition of railings/slab/approach for Bridges	S/SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

(Signature)

A.E. Balsa

NAME:

Asim Kumar