

FIELD INSPECTION REPORT

| | | | |
|--|---|-----------|------------|
| DATE OF INSPECTION: | 06/12/2020 | DISTRICT: | Purnea |
| DIVISION: | Dhamdaha | LENGTH: | - 2.670 km |
| NAME OF THE ROAD: | Bhawanipur Approach Road to Sahidganj | | |
| SCHEME/PROGRAMME: | MAINTENANCE - | | |
| PACKAGE No: | ROAD ID No.: | | |
| STATUS OF THE PROJECT: | ONGOING/COMPLETED/UNDER MAINTENANCE | | |
| WORK IS A CASE OF: | NEW CONNECTIVITY/UP GRADATION/MAINTENANCE | | |
| SL.NO | PARAMETERS TO BE CHECKED | REMARKS | |
| 1 | PAVEMENT | | |
| A | ROAD JUNCTION CONDITION | S | |
| B | CONDITION OF SURFACING | S | |
| C | RIDING QUALITY | S | |
| D | ROAD CAMBER | S | |
| E | WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT | N/A | |
| F | CONTRACTION JOINTS PROVIDED OR NOT (CC PAVEMENT) | N/A | |
| G | COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY | S | |
| 2 | CROSS DRAINAGE | | |
| A | CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING | N/A | |
| B | CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS | N/A | |
| C | CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES | N/A | |
| 3 | ROAD FURNITURE | | |
| A | WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED | S | |
| 4 | COMPLIANCE HISTORY | | |
| A | STATUS OF ATR's & ANY OTHERS | N/A | |
| OVERALL RATING | S | | |
| SATISFACTORY(S) | | | |
| SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) | | | |
| UNSATISFACTORY(U) | | | |

NAME:
DESIGNATION:

ICM. Kum
Junior Engrg.

ICM. Kum
6/12/2020
SIGNATURE