	FIELD INSPECTION REPORT	
DATE OF INSPECTION:	07/12/2020 DISTRICT: Purnea	
DIVISION:	Dhoimdaha LENGTH: 4.350 KM Kanalpur Jagir to Sansani Bhatatar MR-3054 MAINTENANCE	
NAME OF THE ROAD:	Kamelpur Tagir to Santani Bhatotar	
SCHEME/PROGRAMME:	MR-3054 MAINTENANCE	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRAVATION/MAINTENANCE	
SLNO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	N.A
В	CONDITION FO SURFACING	N.A
С	RIDING QUALITY	N.A
D	ROAD CAMBER	N.A
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	N. 4
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N. A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N. 4
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N. A N. A
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	`5'
4	COMPLIANCE HISTORY	
Α	STATUS OF ATR"s & ANY OTHERS	N.A
OVERALL RATING	ERALL RATING The work yet is to be Started SATISFACTORY(S)	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
	UNSATISFACTORY(U)	

NAME: Surendra prasad Singh DESIGNATION: Junior Engineer

3/12/2020

SIGNATURE