	FIELD INSPECTION REPORT	
DATE OF INSPECTION:	05/12/2020 DISTRICT: PURLOR Dhoundalia LENGTH: 5.960 KM	
DIVISION:	Dhoundaha LENGTH: 5.960 KM	
NAME OF THE ROAD:	Nathpur to Chahbacela	
SCHEME/PROGRAMME:	MR-3054 MAINTENANCE	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
Α	ROAD JUNCTION CONDITION	N.A
В	CONDITION FO SURFACING	N.A
C	RIDING QUALITY	N. A
D	ROAD CAMBER	N. A
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	N. A
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N· A
2	CROSS DRAINAGE	
	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N. 4
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N. A
	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N. A
c 3	ROAD FURNITURE	
<u> </u>	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	`S'
Α		
4	COMPLIANCE HISTORY	N· A
A	STATUS OF ATR''S & ANY OTHERS	
OVERALL RATING	The work yet is to be starte	a .
	SATISFACTORY(S)	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U)	

NAME: Susendra prosad singh DESIGNATION: Junior Engineer 5/12/2020

SIGNATURE