

# FIELD INSPECTION REPORT I

|                        |                                            |              |          |
|------------------------|--------------------------------------------|--------------|----------|
| Date of Inspection :   | 5.12.2020                                  | District:    | Purnea   |
| Division :             | BALSI                                      | Length (km): | 1.240 KM |
| Name of the Road:      | Tol to Domuhani                            |              |          |
| Scheme/Programme:      | MAINTENANCE                                |              |          |
| Package No.:           |                                            | Road Id No.: |          |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |          |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks           |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------------|
| 1.      | <b>Pavement</b>                                                                                                      |                   |
| a)      | Road Junction condition                                                                                              | S/U NA            |
| b)      | Condition of Surfacing                                                                                               | S/U NA            |
| c)      | Riding Quality                                                                                                       | S/U NA            |
| d)      | Road Camber                                                                                                          | S/U NA            |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No NA         |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No NA         |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No NA         |
| 2.      | <b>Cross Drainage</b>                                                                                                |                   |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U NA        |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U NA        |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U NA        |
| 3.      | <b>Road Furniture</b>                                                                                                |                   |
| a)      | Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained | Yes/No NA         |
| 4.      | <b>Compliance History</b>                                                                                            |                   |
| a)      | Status of ATR's & any others                                                                                         | work not awarded. |

Overall Rating :


Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

NA

  
 (Signature) A.B.  
 Baisa

NAME:

ASIM KUMAR