

FIELD INSPECTION REPORT

Date of Inspection :	5.12.2020	District:	Pune
Division :	BALSI	Length (km):	2.650 KM
Name of the Road:	TOL to Raibher		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes No NA
g)	Compaction of flank/slope & raincuts if any	Yes No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SRI/U NA
c)	Condition of railings/slab/approach for Bridges	✓SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

"S"

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)
5/12/2020

A.E. Balsa

NAME:

Asim Kumar