

# FIELD INSPECTION REPORT

Date of Inspection: 6/12/2020 District: PUNJAB  
 Division: Road Length (km): 7.275 km  
 Name of the Road: Tanagachi to Bilapur  
 Scheme/Programmes: MAINTENANCE  
 Package No.: Road Id No.:  
 Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance  
 Work is a case of: ☒ New Connectivity/ ☐ Upgradation/ ☐ Maintenance

| Sl. No. | Parameters to be checked                                                                                            | Remarks  |
|---------|---------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                     |          |
| a)      | Road Junction condition                                                                                             | Nil NA   |
| b)      | Condition of Surfacing                                                                                              | Nil NA   |
| c)      | Riding Quality                                                                                                      | ✓        |
| d)      | Road Camber                                                                                                         | ✓        |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                        | Yes NA   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                    | Yes NA   |
| g)      | Compaction of Bank/slope & raincuts if any                                                                          | ✓ Yes    |
| 2.      | <b>Cross Drainage</b>                                                                                               |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                | S SRI NA |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                            | S SRI NA |
| c)      | Condition of railings/slab/approach for Bridges                                                                     | S SRI NA |
| 3.      | <b>Road Furniture</b>                                                                                               |          |
| a)      | Whether sign boards/informatory/cautionary Board km & 20m stones/Pavement road markings are provided and maintained | Yes      |
| 4.      | <b>Compliance History</b>                                                                                           |          |
| a)      | Status of ATR's & any others                                                                                        |          |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Work In Progress

"S"

6/12/2020

(Signature)

Balsa

NAME:

Ashu Kumar